Work Orde Tuesday, Novemb												Page
Item ID: Revision ID:	D3914-041			Accept					Setup	Start		
	11/23/2010	d Assembly (350) Start Qty: 1.00 Req'd Qty: 1.00			Cust Item I Customer:	D:				Stop		
Approvals:	Process Plan:QC:		Date: 0-11-29	7 Tooling: SPC (Y/N):		ite:	-	I	Run	Start Stop		
Sequence ID/ Work Center ID		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rejo Qty		Reject Number	Insp. Stamp
Draw Nbr D3914	Revis	sion Nbr			,	·						<u> </u>
100 Large Fab Large Fab		Memo 1- assemble 2- weld hing ***inspect t 3- tack weld	ribs , weld as per dwg D3: e (3) and Mounting bracker efore welding mesh*** mesh on basket as per dwg et to place mesh correctly contacts	0.00 914 using DT9607A ets as per dwg D3914 g D3914	olate before			SY	101	121	116	(L)

110

QC

Quality Control

QC9- Inspect visual per QSI004- Fusion Welds

0.00

Memo

0.00

PE 10.12.17 1

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			WC	ORK ORDER CHANGE	ES			·····	
DATE	STEP	PROC	EDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	_ Fault Cate	gory:	NCR: Yes	No DQA	\ :	Date:	
	R	esolution:	_ Dispositio	n:	QA: N/C Cld	osed:		Date: _	and the state of t
NCR:		W	ORK ORD	ER NON-CONFORMA	NCE (NCR)			
DATE -	STEP	Description of NC		Corrective Action Section		Verifica		Approval	Approval
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sectio	n C	Chief Eng	QC Inspector

								•	
									· · · · · · · · · · · · · · · · · · ·

Work Order ID 64028

Required Date: 11/30/2010

Tuesday, November 23, 2010 8:06:37 AM



Page 2

Item ID:

D3914-041

Accept



Setup Start



Revision IP:

Item Name:

Long Basket Lid Assembly (350)

Start Date:

11/23/2010

Start Oty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____ Date: ____

Tooling:

Date:

Run

Start

Stop



QC:

Date:_____

SPC (Y/N):

Set Up/

Run Hours

Tool ID

Date:

Tool # Plan

Code

Accept Qty

Reject **Qty**

Reject Insp. Number Stamp

Work Center ID 120

Sequence ID/

QC

Quality Control

Operation **Description**

QC6- Inspect dimensions to drawing

Memo

10/12/20

1 Bl 10-12-20

130

Powdercoat

Powder Coating

Black Sandtex(Ref:4.3.5.7) per QSI005 4.3

0.00

0.00

*** mask sides of binge prior to powdercoat***

Start Time: Oven Temperature

140

HandFinish

Hand Finishing

Wing Walk as per dwg QSI005 4.4 Batch MU15 7996

10/12/20 1 0

1- Mask data plate and apply wing walk on outside surface of mesh as per dwg

2- Install placard and label as per dwg

Dart Aerospace

W/O:			W	ORK ORDER CHANG	GES						
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
					ļ						
Part No	•	PAR #:	Fault Cat	egory:	NCR: Y	es No D	QA:	Date: _	·		
Resolution:			Dispositi	Disposition: QA: N/C Closed: Date:							
NCR:		· :	WORK OR	DER NON-CONFORM	IANCE (N	CR)					
DATE	STEP	Description of NC		*	ction B	Ver	ification	Approval	Approval		
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng			ection C	Chief Eng	QC Inspector		
								ļ			
	·										
				,							
	1 1										

Work Order ID 64028

Required Date: 11/30/2010

Tuesday, November 23, 2010 8:06:37 AM



Page 3

Item ID:

D3914-041

Accept

Setup Start

Stop



Revision ID:

Item Name:

Long Basket Lid Assembly (350)

Start Date:

11/23/2010

Start Qty: 1.00

Req'd Qty: 1.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: __________

Date:

Tooling: SPC (Y/N):

Date: Date:

Run

Start Stop



Sequence ID/ **Work Center ID**

150

Quality Control

Operation Description

QC3- Inspect Part Finish

Memo

Date: _____

Set Up/ **Run Hours**

0.00

0.00

Tool ID

Tool # Plan Code

Accept Qty

Reject Qty

Reject Insp. Number

Stamp

160

Packaging

Packaging

Identify as per dwg & Stock Location: 6 Y

Memo

0.00

170

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

/o: WORK ORDER CHANGE														
STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mar	Approval QC Inspector						
		-					1700 11191							
							}							
•	PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQ	A:	_ Date: _							
R	esolution:	Dispositi	on:	_ QA: N/C C	osed:		Date: _							
	\	WORK ORI	DER NON-CONFORMA	ANCE (NCF	R)									
STED	Description of NC				Verifi	cation	Approval	Approval						
JILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	ion C	Chief Eng	QC Inspector						
				•										
		•												
İ														
		:PAR #:	STEP PROCEDURE CH PAR #: Fault Cat Resolution: Dispositi WORK ORE STEP Description of NC Section A Initial	STEP PROCEDURE CHANGE PAR #: Fault Category: Resolution: Disposition: WORK ORDER NON-CONFORMA STEP Description of NC Section A Corrective Action Section A Corrective Action Description	PAR #: Fault Category: NCR: Yes Resolution: Disposition: QA: N/C CI WORK ORDER NON-CONFORMANCE (NCF STEP Description of NC Section A	STEP PROCEDURE CHANGE By Date PAR #: Fault Category: NCR: Yes No DQ Resolution: Disposition: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC	STEP PROCEDURE CHANGE By Date Qty	STEP PROCEDURE CHANGE By Date Qty Chief Eng/Prod Mgr :PAR #:Fault Category:NCR: Yes No DQA:Date:						

Picklist Print

Tuesday, November 23, 2010 8:06:42 AM

Work Order ID: 64028

Parent Item: D3914-041

Parent Item Nam. Long Basket Lid Assembly (350),



Start Date: 11/23/2010

Raquired Date: 11/30/2010

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev:A new issue DD 10.03.19 verified by:EC

IPP Rev:B

a	s per dwg revB Dl	D 10.08.18 verifi	ed by:E	C									
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2581 Mounting Bracket		Manufactured	No			100	Each	31.0000	2	2 1	11011	a/1	
				Locatio	<u>n</u>	Loc	Qty	Loc Code					
				WA			31		-	(3)	_		
					61953 63493		20 11			(gx)			
D3914-1 .		Manufactured	No		03493	100	Each	4.0000	2	2	_		
Rib		wianulactured				700	Euon			1	1 10	119/1	6
				Locatio	<u>n</u>	Loc	<u>Qty</u>	Loc Code					
				WA			4		_	<u> </u>	_		
,					63609		4			$(\chi'Q)$	<u></u>		
D3914-7	4 1.1681	Manufactured	No			100	Each	4.0000	2	2	١.		
Rib										_0	1 10/	19/11	c
				Locatio	<u>n</u>	Loc	Oty	Loc Code					
				WA			4		-		_		
•					63631		4			(8x)	_		
D4016-3	III (68)	Manufactured	No			100	Each	4.0000	3	3		Λ	
Hinge Half, Lid										B638	55 D		गिविवार
				<u>Locatio</u>	<u>on</u>	Loc	<u>Oty</u>	Loc Code					
				WA			4				_		
					63256		4			!x			

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES												
DATE	STEP	PROC	EDURE CH	IANGE		Ву	Date C	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
									*					
			·		100									
Part No	·	PAR #:	_ Fault Ca	tegory:	N	CR: Yes	No DQA:		_ Date: _					
			Disposition: QA: N/C Closed: Date											
NCR:		. We	ORK OR	DER NON-CONI	FORMANC	E (NCF	R)							
DATE	STEP	Description of NC	I	Corrective Action		Verific			Approval	Approval				
	0.2.	Section A	Initial Chief Eng	Action Desc Chief En	eription g	Date		C	Chief Eng	QC Inspector				
										1.5				
		•					,							
	_								* .					
									-					
							•							
					·									

Tuesday, November 23, 2010 8:06:42 AM

Work Order ID: 64028

Parent Item

D3914-041

Parent Jtem Name: Long Basket Lid Assembly (35)



Start Date: 11/23/2010

Required Date: 11/30/2010

Start Oty: 1.00

Required Oty: 1.00

D4018-5

Manufactured

No

100

Each

33.0000

W/10/12/16

D4020-5

Mesh (350 Basket Long, Lid)

Manufactured No

Location

WA

63610

100

Loc Qty

33

33 Each

1.0000

Loc Code

B63684 (1) AS 10/12/16

/D4021-3

Data Plate

No Manufactured

60643

Location

Location

Location

WA

WA

WA

100 Each

Loc Oty

Loc Code

1.0000

JD4035-041

Lid Rib Assembly, Fwd (350 Basket)

No Manufactured

56050

100

100

Each

Loc Qty

1.0000

Loc Code

✓ _{D4035-043}

Lid Rib Assembly, Aft (350 Basket)

Manufactured No

61066

Loc Qty Each Loc Code

1.0000

ly rollalis

Location Loc Qty Loc Code WA 61067

Dart .	Aeros	pace	Ltd
--------	-------	------	-----

W/O:			WC	ORK ORDER CHANG	ES			
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date (Qty Approval Chief Eng / Prod Mgr	Approval QC Inspector
							*	
		,						
		·						
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA:	Date:	_
	· R	esolution:	Dispositio	n:	QA: N/C C	losed:	Date:	
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NC	₹)		
DATE	STEP	Description of NC		ion B	Verificat	tion Approval	Approval	
DAIL	SILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date		C Chief Eng	QC Inspector
				•				
`								
,	ī							

Picklist Print

Tuesday, November 23, 2010 8:06:42 AM

Work Order ID: 64028

Parent Item:

D3914-041

Parent Item Name: Long Basket Lid Assembly (350)



Start Date: 11/23/2010

Required Date: 11/30/2010

Page 3

Start Qty: 1.00

Required Qty: 1.00

D2728-3

Dart Logo label


Manufactured No

140

Each


0.0000

Dart Ae	rospace	e Ltd									• .
W/O:			W	ORK ORDER CH	ANGE	S					
DATE	STEP	PRO	PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	Part No: PAR #:		Fault Category:			NCR: Yes No DQA				Date:	
	R	esolution:	Dispositi	on:		QA: N	I/C Clo	sed:		Date:	
NCR:		V	VORK ORI	DER NON-CONFO	RMAN	VCE (NCR)			1420	
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Action Descrip Chief Eng	Section otion		Sign & Date		cation on C	Approval Chief Eng	Approval QC Inspector
					······						
		·									




Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
						1			1 Tod Wgi		
Part No		PAR #:	Fault Cate	gory:	NCR: Y	es N	o DQ .	A :	_ Date: _		
Resolution:		Disposition: Q			Clos	ed:		Date: _			
NCR:			WORK ORD	ER NON-CONFORMA	NCE (N	CR)				·	
DATE	STEP	Description of NC	Description of NC Corrective Action			Veritic			Approval	l Approval	
DATE		Section A	Initial Chief Eng	Action Description Chief Eng		n & ate	Secti		Chief Eng	QC Inspector	
							•				
		- And the state of									




Dar	tΑ	ero	SD	ace	Ltd
-----	----	-----	----	-----	-----

W/O:		WORK ORDER CHANGES										
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No	•	PAR #:	Fault Cat	egory:	NCR: Yes	No DQ	\ :	_ Date: _				
Resolution		esolution:	Disposition: QA			osed:		Date: _				
NCR:		,	WORK ORE	DER NON-CONFORMA	NCE (NCF	R)	<u> </u>					
DATE	STEP	Description of NC	Description of NC Corrective Action			Verific	ication	Approval	Approval			
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section	Section C	Chief Eng	QC Inspector			
									<u> </u>			
•												



Dart	Aeros	pace	Ltd

				* . ***						
W/O:			W	ORK ORDER CHAN	GES					
DATE STEP		PROCEDURE CHANGE			В	У	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	<u> </u>	PAR #:	Fault Cate	gory:	NCB: \	es N	o DQ /	۱	Date:	
		Disposition: QA								
NCR:				ER NON-CONFORM				,		
NCh.							Ι			
DATE	STEP	Description of NC Section A	Corrective Action Initial Action Description		ection B	gn &	Verification Section C		Approval Chief Eng	Approval QC Inspector
		Occion A	Chief Eng	Chief Eng		ate	Jectin		Offici Ling	QO Mapecior
								<u> </u>		



Dart	Aeros	pace	I td
Duit	70103	Dacc	

W/O:		WORK ORDER CHANGES									
DATE	STEP	PRO	PROCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
-											
								:	·		
		•						,			
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA	.:	Date: _			
Resolution		esolution:	Disposition:			Closed:	Date:				
NCR:		,	WORK ORD	ER NON-CONFORM	ANCE (NC	R)	1				
DATE	STEP	Description of NC			ction B	Verifica	ation	Approval	Approval		
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat		n C	Chief Eng	QC Inspector		
						:					
					•						
				t							
									}		
			1	÷		1					